

Inspection Photos
Location Name: Hotchkiss Water Storage Facility
Facility ID #421193



Southern Pit (Facility ID #454880). Rust colored staining at gathering line outlets.



Bubbled up portion of liner in southern pit.

Inspection Photos
Location Name: Hotchkiss Water Storage Facility
Facility ID #421193



View of southern pit liner exposed.



Northern pit (Facility ID #454881).