

Inspection Photos June 7, 2019

**Location Name: Kelton "A" – Spill/Release/Remediation Inspection (Spill Point #449650) (remediation #10548)
NWNW Section 8 – Township 2 South - Range 64 West
Adams County**



From spill/release/remediation location looking north to Kelton "31-8" well head.



From spill/release/remediation location looking northwest

Inspection Photos June 7, 2019

Location Name: Kelton "A" – Spill/Release/Remediation Inspection (Spill Point #449650) (remediation #10548)

**NWNW Section 8 – Township 2 South - Range 64 West
Adams County**



From spill/release/remediation location looking west



From spill/release/remediation location looking SSW

Inspection Photos June 7, 2019

Location Name: Kelton "A" – Spill/Release/Remediation Inspection (Spill Point #449650) (remediation #10548)

**NWNW Section 8 – Township 2 South - Range 64 West
Adams County**



View of remediation area looking toward Kelton "A" 31-8 wellhead (north)



Kelton "A" 31-8 wellhead sign

