

# Inspection Photos

API: 05-055-06077

Operator: OXY USA INC

Inspection Date: 6/11/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06077 | Date: 6/11/2019

## Inspection Photos



**Photo 1.** There are numerous noxious weeds (Common mullein) near all the wells in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06077 | Date: 6/11/2019