

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/11/2019

Submitted Date:

06/11/2019

Document Number:

692602006

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
304101 \_\_\_\_\_ Welsh, Brian \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone | Email                           | Comment |
|---------------|-------|---------------------------------|---------|
| Beard, Alyssa |       | regulatory@foundationenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 254063      | WELL | PR     | 04/11/1997  | GW         | 125-07941 | ROSE 24-18    | PR          |

**General Comment:**

Routine Inspection

**Location****Lease Road:**

|                    |                                     |       |  |
|--------------------|-------------------------------------|-------|--|
| Type               | Other                               |       |  |
| comment:           | Access wellhead through farm ground |       |  |
| Corrective ActionL |                                     | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |                        |       |  |
|--------------------|------------------------|-------|--|
| Type               | WELLHEAD               |       |  |
| Comment:           | Lease sign by wellhead |       |  |
| Corrective Action: |                        | Date: |  |

**Emergency Contact Number:**

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  | Date: _____ |
| Corrective Action: |  |             |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |                                                                                                                                                                       |       |      |             |           |         |    |               |    |
|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 254063                                                                                                                                                                | Type: | WELL | API Number: | 125-07941 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                                                                                                                                                                       |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Casing production. Central meter run for (Rose 1-18, 3-18, 4-18, 13-18, 22-18, 23-18, 24-18, 32-18, 33-18, 43-18, 44-18, Shay 11-18) 1750' ENE @ Rose 1-18 |       |      |             |           |         |    |               |    |
| Corrective Action:   |                                                                                                                                                                       |       |      |             |           |         |    | Date:         |    |

Reclamation - Storm Water - Pit

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other            | Pass            | Other                   | Pass                  |               |                          |         |

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT