

Inspection Photos

Location Name: COTTONTAIL PASS UNIT 31-2

API#: 05-071-06386

INSP. #: 695100854



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN/ CURRENT OPERATOR IS NOT POSTED ON WELL SIGN. 911 IS NOT INCLUDED IN EMERGENCY CONTACT. COMPLY WITH 210.b. CA DATE 7/11/19.



Inspection Photos

Location Name: COTTONTAIL PASS UNIT 31-2

API#: 05-071-06386

INSP. #: 695100854



PHOTO 3: Vacuum pump observed on well without COGCC approval. Provide COGCC with documentation showing approval of use of vacuum pump. CA DATE 6/26/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources