

Inspection Photos
Location Name: APRIL-67N60W /14SWNW
Location #: 317498



Photo #1

April 12-14 (05-123-05372) Wellsite
Shut-In | SI



Photo #2

April 12-14, Dryer #1 Battery
Shut-down

Inspection Photos
Location Name: APRIL-67N60W /14SWNW
Location #: 317498



Photo #3
April 12-14, Dryer #1 Battery
Unused Equip (Steps / Walkways) from removed oil tanks
from prior insp.



Photo #4
April 12-14, Dryer #1 Battery
Unused Equip (Steps / Walkways) from removed oil tanks – NOW removed

Inspection Photos
Location Name: APRIL-67N60W /14SWNW
Location #: 317498



Photo #5
April 12-14, Dryer #1 Battery
*Stain appears on oil tank
from prior insp.*



Photo #6
April 12-14, Dryer #1 Battery
*Stain appears on oil tank
NOW appears mitigated*

Inspection Photos
Location Name: APRIL-67N60W /14SWNW
Location #: 317498



Photo #7
April 12-14, Dryer #1 Battery - Separator
*Stained soil appears beneath separator
from prior insp.*



Photo #8
April 12-14, Dryer #1 Battery - Separator
*Stained soil appears beneath separator
NOW appears mitigated*

Inspection Photos
Location Name: APRIL-67N60W /14SWNW
Location #: 317498



Colorado Oil & Gas Conservation Commission
40.57729, -104.06682, 1470.0m, 285°
2018/08/17 01:56:30 PM

Photo #9

April 12-14, Dryer #1 Battery - Separator
*Stained soil appears beneath separator
from prior insp.*



Colorado Oil & Gas Conservation Commission
40.57732, -104.06688
06/12/2019 12:38:10 PM

Photo #10

April 12-14, Dryer #1 Battery - Separator
*Stained soil appears beneath separator
NOW appears mitigated*

Inspection Photos
Location Name: APRIL-67N60W /14SWNW
Location #: 317498



Photo #11
April 12-14, Dryer #1 Pit Area
*Gaps appear on / beneath pit netting
from prior insp.*



Photo #12
April 12-14, Dryer #1 Pit Area
*Gaps appear on / beneath pit netting
NOW appears mitigated*

Inspection Photos
Location Name: APRIL-67N60W /14SWNW
Location #: 317498



Photo #13
April 12-14, Dryer #1 Pit Area
*Oil skim appears on pit water surface
from prior insp.*



Photo #14
April 12-14, Dryer #1 Pit Area
*Oil skim on pit water surface
NOW appears mitigated*