

Pit Status Evaluation Form

Pit Overview:

Pit Name: Thomas "X"	Facility ID: 118057
Current Status: Unknown	Status Date: 09/23/1999
Current Operator: Buttes Gas & Oil Co. / 12266	
Updated Operator:	
Form 15 Pit Permit Doc #: 658477	Permit Date: 11/3/1971
Related Facilities: Location ID 404964; Well Thomas, A L 1 API 05-123-05261	

County: Weld			
Township: 7N	Range: 58W	Section: 31	QQ: SESW
Original Latitude/ Longitude: 40.525527 / -103.910676			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|--------------------------|---|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: 658477 | Date: 11/3/1971 |
| <input type="checkbox"/> | Field Inspection(s) – Doc #: | Date: |
| | Doc #: | Date: |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 1/10/1985

Timing of Pit Closure:

Final well producing to pit was plugged 1985

Pit Status Review Summary:

Pit was permitted in 1971. Final well producing to pit was plugged 1985. Site passed reclamation inspection. No viable Operator