

Inspected Facilities

Facility ID: 241507 Type: WELL API Number: 123-09296 Status: PR Insp. Status: PR

COGCC Comments

Comment	User	Date
Follow up inspection to Doc# 688401287 in response to FIRR #401953933. Based on photos submitted by operator corrective actions have been completed. (photos attached to FIRR)	silverr	06/14/2019