

Final Reclamation Inspection

June 3, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

API: 05-123-05445

Inspection Document #: 697500203

Weld County, CO

NENE Section 1 T7N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BLACK HOLLOWS UT-UPRR #7
API: 05-123-05445



Photo 1. Photo taken from the entrance of the location, facing South. Operator has performed the previous corrective action to perform final reclamation activities at the well location and access road. At the time of this inspection, germination was apparent throughout the access road.