

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/14/2019

Submitted Date:

06/14/2019

Document Number:

685101139

**FIELD INSPECTION FORM**

Loc ID 418522	Inspector Name: MEDINA, JUSTIN	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 5 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																
<b>Operator Information:</b> OGCC Operator Number: 47120 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Address: P O BOX 173779 City: DENVER State: CO Zip: 80217-				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>																																																																																
<b>Contact Information:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>,</td> <td></td> <td>COGCCinspections@anadarko.com</td> <td>All Inspections</td> </tr> </table>					Contact Name	Phone	Email	Comment	,		COGCCinspections@anadarko.com	All Inspections																																																																								
Contact Name	Phone	Email	Comment																																																																																	
,		COGCCinspections@anadarko.com	All Inspections																																																																																	
<b>Inspected Facilities:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>418517</td><td>WELL</td><td>PA</td><td>07/06/2017</td><td>OW</td><td>123-31941</td><td>BADDING 8-26SX</td><td>PA</td></tr> <tr><td>418520</td><td>WELL</td><td>SI</td><td>01/01/2019</td><td>OW</td><td>123-31942</td><td>BADDING 1-26</td><td>SI</td></tr> <tr><td>418521</td><td>WELL</td><td>PR</td><td>01/01/2019</td><td>OW</td><td>123-31943</td><td>BADDING 1-26SX</td><td>PR</td></tr> <tr><td>418523</td><td>WELL</td><td>PR</td><td>09/01/2017</td><td>OW</td><td>123-31944</td><td>BADDING 2-26</td><td>PR</td></tr> <tr><td>418524</td><td>WELL</td><td>SI</td><td>12/01/2017</td><td>OW</td><td>123-31945</td><td>BADDING 2-26SX</td><td>SI</td></tr> <tr><td>418525</td><td>WELL</td><td>PR</td><td>11/01/2018</td><td>GW</td><td>123-31946</td><td>BADDING 41-26</td><td>PR</td></tr> <tr><td>418534</td><td>WELL</td><td>PR</td><td>09/01/2017</td><td>OW</td><td>123-31949</td><td>BADDING 27-26</td><td>PR</td></tr> <tr><td>418547</td><td>WELL</td><td>PR</td><td>09/01/2017</td><td>OW</td><td>123-31951</td><td>BADDING 24-26</td><td>PR</td></tr> <tr><td>418973</td><td>WELL</td><td>PR</td><td>11/01/2018</td><td>OW</td><td>123-32083</td><td>BADDING 8-26</td><td>PR</td></tr> </tbody> </table>					Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	418517	WELL	PA	07/06/2017	OW	123-31941	BADDING 8-26SX	PA	418520	WELL	SI	01/01/2019	OW	123-31942	BADDING 1-26	SI	418521	WELL	PR	01/01/2019	OW	123-31943	BADDING 1-26SX	PR	418523	WELL	PR	09/01/2017	OW	123-31944	BADDING 2-26	PR	418524	WELL	SI	12/01/2017	OW	123-31945	BADDING 2-26SX	SI	418525	WELL	PR	11/01/2018	GW	123-31946	BADDING 41-26	PR	418534	WELL	PR	09/01/2017	OW	123-31949	BADDING 27-26	PR	418547	WELL	PR	09/01/2017	OW	123-31951	BADDING 24-26	PR	418973	WELL	PR	11/01/2018	OW	123-32083	BADDING 8-26	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																													
418517	WELL	PA	07/06/2017	OW	123-31941	BADDING 8-26SX	PA																																																																													
418520	WELL	SI	01/01/2019	OW	123-31942	BADDING 1-26	SI																																																																													
418521	WELL	PR	01/01/2019	OW	123-31943	BADDING 1-26SX	PR																																																																													
418523	WELL	PR	09/01/2017	OW	123-31944	BADDING 2-26	PR																																																																													
418524	WELL	SI	12/01/2017	OW	123-31945	BADDING 2-26SX	SI																																																																													
418525	WELL	PR	11/01/2018	GW	123-31946	BADDING 41-26	PR																																																																													
418534	WELL	PR	09/01/2017	OW	123-31949	BADDING 27-26	PR																																																																													
418547	WELL	PR	09/01/2017	OW	123-31951	BADDING 24-26	PR																																																																													
418973	WELL	PR	11/01/2018	OW	123-32083	BADDING 8-26	PR																																																																													
<b>General Comment:</b> <div style="height: 100px; border: 1px solid black;"></div>																																																																																				

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Pump Jack

# 2

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 5

Comment:

Corrective Action:

Date:

Type: Bradenhead

# 8

Comment:

Corrective Action:

Date:

Type: Prime Mover

# 2

Comment: Electric motor

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: <u>418517</u>	Type: <u>WELL</u>	API Number: <u>123-31941</u>	Status: <u>PA</u>	Insp. Status: <u>PA</u>
Facility ID: <u>418520</u>	Type: <u>WELL</u>	API Number: <u>123-31942</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>418521</u>	Type: <u>WELL</u>	API Number: <u>123-31943</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>418523</u>	Type: <u>WELL</u>	API Number: <u>123-31944</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>418524</u>	Type: <u>WELL</u>	API Number: <u>123-31945</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>418525</u>	Type: <u>WELL</u>	API Number: <u>123-31946</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>418534</u>	Type: <u>WELL</u>	API Number: <u>123-31949</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>418547</u>	Type: <u>WELL</u>	API Number: <u>123-31951</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>418973</u>	Type: <u>WELL</u>	API Number: <u>123-32083</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

**Producing Well**Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. Continuing Education Inspection.	medinaj	06/14/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101140	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4850449">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4850449</a>