

Inspection Photos
Location Name: Monfort E 19-12
Location ID: 330236



Photo 1 – Wellhead



Photo 2 – Tank Battery

Inspection Photos
Location Name: Monfort E 19-12
Location ID: 330236



Photo 3 – Trash from previous Inspection Doc ID #679600456



Photo 4 – Trash has been removed.