

Interim Reclamation and Stormwater Inspection

June 10, 2019

Operator: PDC ENERGY INC - #69175

Location ID: 319511

Inspection Document #: 697500207

Weld County, CO

SWSW Section 7 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Zeiler /SW-7 Pad
Location ID: 319511



Photo 1. Photo taken from the southwestern location, facing South. Operator has failed to implement long-term stormwater BMPs to prevent sediment laden stormwater from leaving location. Photo illustrates gully erosion with sediment discharge off location.

Inspection Photos
Location Name: Zeiler /SW-7 Pad
Location ID: 319511



Photo 2. Photo taken from the southern location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Zeiler /SW-7 Pad
Location ID: 319511



Photo 3. Photo taken from the southern location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Zeiler /SW-7 Pad
Location ID: 319511



Photo 4. Photo taken from the southern location, facing East. Photo illustrates sediment discharge off location.

Inspection Photos
Location Name: Zeiler /SW-7 Pad
Location ID: 319511



Photo 5. Photo taken from the southern location, facing North. See comments under Photo 4.