



**Inspected Facilities**

Facility ID: 274677 Type: WELL API Number: 071-08248 Status: PR Insp. Status: PR

**COGCC Comments**

Comment	User	Date
Follow up inspection to Doc# 688401857 in response to FIRR #40213989. Based on photos submitted by operator corrective actions have been completed. (photos attached to FIRR)	silverr	06/17/2019