

# Inspection Photos

API: 05-009-06117

Operator: SOVEREIGN OPERATING

Inspection Date: 6/13/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06117 | Date: 6/13/2019

## Inspection Photos



**Photo 1.** Facing east toward the location, Crop has not reestablished.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06117 | Date: 6/13/2019

## Inspection Photos



**Photo 2.** There is a piece of pipe debris that remains at the site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06117 | Date: 6/13/2019

## Inspection Photos



**Photo 3.** Facing north at the surrounding crop.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06117 | Date: 6/13/2019