

Inspection Photos

API: 05-009-06583

Operator: NORSTAR PETROLEUM

Inspection Date: 6/13/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06583 | Date: 6/13/2019

Inspection Photos



Photo 1. An abandoned pipe riser remains at the location.

Lat/Long:37.17655,-102.06051



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06583 | Date: 6/13/2019

Inspection Photos




Photo 2. Facing west at the well site. Crop has not reestablished at the area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06583 | Date: 6/13/2019

Inspection Photos



Photo 3. Facing south at the surrounding crop.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06583 | Date: 6/13/2019