

Inspection Photos

Location Name: LORENCITO 4-15-34-66

API#: 05-071-07582

INSP. #: 695100909



Colorado Oil & Gas Conservation Commission
37.09007, -104.77483, 2195.0m, 167°
2019/06/17 14:37:28

PHOTO 1: WELLHEAD



Colorado Oil & Gas Conservation Commission
37.09047, -104.77444, 2202.0m, 125°
2019/06/17 14:36:37

PHOTO 2: WELL SIGN



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: LORENCITO 4-15-34-66
API#: 05-071-07582
INSP. #: 695100909



PHOTO 3: 3 PACHES OF IMPACTED SOIL UNDER PUMPJACK SKID NEAR MOTOR. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 7/17/19.



PHOTO 4: UNUSED EQUIPMENT. REINSTALL PUMPJACK FENCE OR REMOVE UNUSED FENCE PANELS PER RULE 603.f. CA DATE 7/17/19.



Inspection Photos

Location Name: LORENCITO 4-15-34-66

API#: 05-071-07582

INSP. #: 695100909



**PHOTO 5: UNUSED EQUIPMENT 2" PIPE STORED ON
LOCATION. REMOVE UNUSED EQUIPMENT PER RULE 603.f.
CA DATE 7/17/19.**