

Caerus Piceance LLC  
API # 05-045-12289  
Inspection # 696600155



**Photo #1** Photo from entrance of location.



**Photo #2** Separators on location.

Caerus Piceance LLC  
API # 05-045-12289  
Inspection # 696600155



Photo #3 Photo of tank Battery




Photo #4 Photo of Wellheads





Photo # 5 Photo of unused equipment or trash on location



Photo # 6 Photo of unused equipment or trash on location



Caerus Piceance LLC  
API # 05-045-12289  
Inspection # 696600155



Photo # 7 Photo of unused equipment or trash on location



Photo # 8 Photo of unused equipment or trash on location



Caerus Piceance LLC  
API # 05-045-12289  
Inspection # 696600155



**Photo # 9 Photo of unused equipment or trash on location.  
No Dead Man found**



**Photo # 10 Photo of unused equipment or trash on location.  
No Dead Man found**

Caerus Piceance LLC  
API # 05-045-12289  
Inspection # 696600155



**Photo #11 Tank Battery sign located at unit. Sign missing information.**