

Caerus Piceance LLC
API # 05-045-12388
Inspection # 696600157



Photo #1 Photo from entrance of location.



Photo #2 Separators on location.

Caerus Piceance LLC
API # 05-045-12388
Inspection # 696600157



Photo #3 Photo of tank Battery



Photo #4 Photo of Wellheads

Caerus Piceance LLC
API # 05-045-12388
Inspection # 696600157



Photo # 5 Deadman not marked on location



Photo # 6 Multiple Deadman on location not marked

Caerus Piceance LLC
API # 05-045-12388
Inspection # 696600157



Photo #7 Deadman not marked on location

Caerus Piceance LLC
API # 05-045-12388
Inspection # 696600157



Photo #8 Tank Battery sign located at unit. Sign missing information.