

BP L48 San Juan




Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jun 18, 2019 7:57:36 AM MDT
Server Receive Date:	Jun 18, 2019 7:59:03 AM MDT
Reference Number:	20190618-18109328637
Location:	557 Airpark Dr, Durango, CO 81303, USA Jun 18, 2019 7:57:31 AM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	May 9, 2019
Well Name	REA GAS UNIT 18U-03 2
API Number	50670870100
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Seeding Other

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Completed work description

Seeding and mulching of hillside