



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jun 7, 2019 5:27:10 PM MDT
Server Receive Date:	Jun 7, 2019 5:28:33 PM MDT
Reference Number:	20190607-18108544751
Location:	557 Airpark Dr, Durango, CO 81303, USA Jun 7, 2019 5:26:23 PM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	Jun 6, 2019
Location Name (Other)	ute 1a - 20 3 and 4
Location API (Other)	06709661
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other Clean Up Land Owner Debris

Picture North to South



Picture South to North



Completed work description

treated hoary cress and removed trash

