



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Jun 10, 2019 5:09:21 PM MDT
Server Receive Date:	Jun 10, 2019 9:09:48 PM MDT
Reference Number:	20190611-18108684850
Location:	Unknown Location

## Information

Name	celkins@gobrainstorm.net
Date	Jun 4, 2019
Well Name	DICKENS GAS UNIT 44-14 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Land Owner Debris Clean Up Contaminated Soils Repaired Berm

## Picture North to South



## Picture South to North



## Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos

