

Inspection Photos

API: 05-009-06612

Operator: CHOLLA PRODUCTION

Inspection Date: 6/13/2019



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06612 | Date: 6/13/2019

Inspection Photos



Photo 1. Facing west toward the location. Crop has not reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06612 | Date: 6/13/2019

Inspection Photos



Photo 2. Facing east toward the location. Crop has not reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06612 | Date: 6/13/2019

Inspection Photos



Photo 3. Facing north at the surrounding crop.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06612 | Date: 6/13/2019