



Form Information

| | |
|----------------------|--|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Clay Elkins (celkins@gobrainstorm.net) |
| Submission Date: | Jun 10, 2019 4:55:20 PM MDT |
| Server Receive Date: | Jun 10, 2019 9:11:11 PM MDT |
| Reference Number: | 20190611-18108683924 |
| Location: | Unknown Location |

Information

| | |
|-----------------|---|
| Name | celkins@gobrainstorm.net |
| Date | Jun 10, 2019 |
| Well Name | MAESTAS GAS UNIT A 1 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Land Owner Debris |

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos

