



Form Information

| | |
|----------------------|--|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Clay Elkins (celkins@gobrainstorm.net) |
| Submission Date: | Jun 10, 2019 5:05:50 PM MDT |
| Server Receive Date: | Jun 10, 2019 9:36:06 PM MDT |
| Reference Number: | 20190611-18108684875 |
| Location: | Unknown Location |

Information

| | |
|-----------------|---|
| Name | celkins@gobrainstorm.net |
| Date | Jun 4, 2019 |
| Well Name | SNOOK GAS UNIT B 1A (MV) |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Contaminated Soils Repaired Berm |

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos

