




## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jun 13, 2019 8:36:09 AM MDT
Server Receive Date:	Jun 13, 2019 8:37:36 AM MDT
Reference Number:	20190613-18108883504
Location:	557 Airpark Dr, Durango, CO 81303, USA Jun 13, 2019 8:35:13 AM MDT [ <a href="#">View Map</a> ]

## Information

Name	colen@horizonenvservices.com
Date	Jun 11, 2019
Well Name	MCCAW SWD #2
API Number	50670871800
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Seeding Erosion Repairs Clean Up Weed Debris

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Completed work description

created diversion ditch and installed rock rundown,  
seeded and hydromulched