



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	May 31, 2019 3:52:50 PM MDT
Server Receive Date:	May 31, 2019 3:52:56 PM MDT
Reference Number:	20190531-18108014076
Location:	557 Airpark Dr, Durango, CO 81303, USA May 31, 2019 3:52:07 PM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	May 31, 2019
Well Name	BAIRD GAS UNIT A 2
API Number	50670970400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Completed work description

Selectively treated musk thistle populations throughout project area.