



## Form Information

Form Name: **Compliance Follow Up Form**  
Submitter Name: Cole Nichols (colen@horizonenvservices.com)  
Submission Date: Jun 14, 2019 8:55:18 AM MDT  
Server Receive Date: Jun 14, 2019 8:56:43 AM MDT  
Reference Number: 20190614-18108977066  
Location: 557 Airpark Dr, Durango, CO 81303, USA  
Jun 14, 2019 8:55:06 AM MDT [ [View Map](#) ]

## Information

Name: colen@horizonenvservices.com  
Date: Jun 13, 2019  
Well Name: MARTINEZ GAS UNIT A 1  
Location Name (Other): Martinez A3  
API Number: 50670982300  
Location API (Other): 0506709822  
Select State: Colorado  
Work type: COGCC Inspection AR  
Action Complete: Compliance Inspection Actions  
Clean Up Weed Debris

## Picture North to South



## Picture South to North



Picture East to West



Picture West to East



Completed work description

mowed in reclamation area