



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Jun 18, 2019 7:12:32 AM MDT
Server Receive Date:	Jun 18, 2019 8:24:40 AM MDT
Reference Number:	20190618-18109325051
Location:	Unknown Location

Information

Name	celkins@gobrainstorm.net
Date	Jun 17, 2019
Well Name	ANNALA FEDERAL GAS UNIT A 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Clean up Operator Debris Clean Up Contaminated Soils Repaired Berm Removed sediment from BMP's

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos

