

Inspection Photos

API#081-05352

Operator: Quicksilver

Inspection Number: 692401096

Inspection Date: 6/13/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:


Overview of Location to North where associated facilities were recently reclaimed.

June 13, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Quicksilver PA Alpha State API#081-05352



Photo#2:
Seeded areas showing emerged vegetation.



Photo#3:
Seeded areas showing emerged vegetation.

June 13, ,2019



Photo#4:
Whitetop on Location. Note vehicle tracks.



Photo#5:
Thistle rosettes on site.

June 13, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Quicksilver PA Alpha State API#081-05352



Photo#6:

View over Location to North east, showing vehicle rutting and tracks.

June 13, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Quicksilver PA Alpha State API#081-05352