

Pit Status Evaluation Form

Pit Overview:

Pit Name: IVEY UNIT	Facility ID: 114342
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: CORAL-CENTRAL OPERATING INC / 20263	
Updated Operator: STARLIGHT RESOURCES LLC - 81825	
Form 15 Pit Permit Doc #: NA	Permit Date: NA
Related Facilities: API # 05-001-07093 (Facility ID 201690), Location 375966	

County: Adams			
Township: 1S	Range: 68W	Section: 11	QQ: NESE
Original Latitude/ Longitude: 39.977502 / -104.961787			
Updated Latitude/ Longitude: 39.976866 / -104.960086			
Basis for Location Change: Location updated based on aerial imagery (circa 1999)			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes: 	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|--|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: NA | Date: NA |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 664653 | Date: 2/7/1989 |
| | Doc #: 316462 | Date: 6/7/1998 |
| | Doc #: 1100914 | Date: 1/25/2002 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2314547 | Date: 2/11/1998 |
| <input checked="" type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: 114353 (UNK), 102384 (CL) | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

Well PA 3/27/2001; passed final inspection 1/25/2002

Pit Status Review Summary:

Duplicate of pit IDs 114353 and 102384. Based on records review, an unlined earthen produced water pit was on location. Well was plugged and passed final reclamation inspection 1/25/2002; location is now part of the E-470 right of way. Pit status has been changed to Closed.

