

Inspection Photos
Location Name: Albert Martinez #1
API: 05-007-06253



Albert Martinez #1 wellhead and pump jack.



Drop out tank with 8 psi on pressure gauge.

Inspection Photos
Location Name: Albert Martinez #1
API: 05-007-06253



Albert Martinez #1 tank battery. Shared secondary containment berm with Nielson #4.



Crude oil release from valve on backside of AST.

Inspection Photos
Location Name: Albert Martinez #1
API: 05-007-06253



Load out valve on backside of AST is stained and wet.



View of crude oil release within secondary containment berm.