

Inspection Photos
Location Name: Bower 10-24
Location ID: 302718



Photo 1: PREVIOUS photo of missing placard on produced water tank



Photo 2: CURRENT photo of placard on produced water tank



Inspection Photos
Location Name: Bower 10-24
Location ID: 302718



Photo 3: PREVIOUS photo of stained soil in east separator house




Photo 4: CURRENT photo of stained soil removed in east separator house