

Inspection Photos  
Location Name: Bower 10-23  
Location ID: 302717



Photo 1: PREVIOUS photo of NO emergency contact # on sign




Photo 2: CURRENT photo of emergency contact # on sign