

Inspection Photos

API: 05-071-09838

Operator: ARP PRODUCTION COMPANY
WAPITI OPERATING LLC

Inspection Date: 6/19/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-09838 | Date: 6/19/2019

Inspection Photos



Photo 1. The culvert along the main road has filled in with sediment.
Lat/Long:37.02493,-104.82831



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09838 | Date: 6/19/2019

Inspection Photos



Photo 2. There is erosion occurring at the outlet culvert. No BMPs installed for outlet protection or to prevent erosion. Lat/Long:37.02425,-104.82919



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09838 | Date: 6/19/2019

Inspection Photos



Photo 3. The culvert along the main road has filled in with sediment.
Lat/Long:37.02425,-104.82919



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09838 | Date: 6/19/2019

Inspection Photos



Photo 4. There is List B noxious weeds growing along the main & access road to the location. (Musk thistle shown in photo)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09838 | Date: 6/19/2019

Inspection Photos



Photo 5. There is List B noxious weeds growing along the main & access road to the location. (Musk thistle shown in photo)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09838 | Date: 6/19/2019

Inspection Photos



Photo 6. Well sign is present. Operator name on sign has not changed yet.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09838 | Date: 6/19/2019

Inspection Photos



Photo 7. There is List B noxious weeds growing at the location. (Musk thistle shown in photo)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09838 | Date: 6/19/2019

Inspection Photos



Photo 8. Guy line anchor not marked.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09838 | Date: 6/19/2019

Inspection Photos



Photo 9. Facing toward the cut slope which is stabilized with vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09838 | Date: 6/19/2019