

Inspection Photos

API: 05-071-07915

Operator: ARP PRODUCTION COMPANY
WAPITI OPERATING LLC

Inspection Date: 6/19/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-07915 | Date: 6/19/2019

Inspection Photos



Photo 1. Stormwater is flowing down the road causing erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 6/19/2019

Inspection Photos



Photo 2. These two diversion ditches are transporting sediment offsite. No BMP's installed. Sediment trap or check dams would prevent sediment transport offsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 6/19/2019

Inspection Photos



Photo 3. Stormwater is running down the road and is scouring the road. No BMP's installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 6/19/2019

Inspection Photos



Photo 4. The photo on left is culvert inlet filled with sediment. Photo right is damaged culvert near outlet. Lat/Long:37.00845,-104.84245



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 6/19/2019

Inspection Photos



Photo 5. This culvert is filled in with sediment and damaged.

Lat/Long:37.00817,-104.84711



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 6/19/2019

Inspection Photos



Photo 6. This diversion ditch is transporting sediment off site. No BMP's installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 6/19/2019

Inspection Photos



Photo 7. Facing toward the location. Red arrow points to List B noxious weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 6/19/2019

Inspection Photos



Photo 8. There is an infestation of Canada thistle along the cut slope. The cut slope is not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 6/19/2019

Inspection Photos



Photo 9. Operator sign is updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07915 | Date: 6/19/2019