

Inspection Photos

API: 05-071-07386

Operator: ARP PRODUCTION COMPANY
WAPITI OPERATING LLC

Inspection Date: 6/19/2019



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07386 | Date: 6/19/2019

Inspection Photos



Photo 1. There is List B noxious weeds growing along the main & access road to the location. (Canada thistle shown in photo)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07386 | Date: 6/19/2019

Inspection Photos



Photo 2. There is erosion occurring down the road and no BMP's are installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07386 | Date: 6/19/2019

Inspection Photos



Photo 3. Well sign is installed and updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07386 | Date: 6/19/2019