

Inspection Photos

API: 05-071-09017

Operator: ARP PRODUCTION COMPANY
WAPITI OPERATING LLC

Inspection Date: 6/19/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09017 | Date: 6/19/2019

Inspection Photos



Photo 1. There are List B noxious weeds along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09017 | Date: 6/19/2019

Inspection Photos



Photo 2. There is dark stained soil around the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09017 | Date: 6/19/2019

Inspection Photos



Photo 3. Operator sign is updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09017 | Date: 6/19/2019