

Inspection Photos

API: 05-071-09051

Operator: ARP PRODUCTION COMPANY
WAPITI OPERATING LLC

Inspection Date: 6/19/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09051 | Date: 6/19/2019

Inspection Photos



Photo 1. The outlet culvert at the location has no BMP's to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09051 | Date: 6/19/2019

Inspection Photos



Photo 2. Operator sign is updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09051 | Date: 6/19/2019

Inspection Photos



Photo 3. There are List B noxious weeds along the south side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09051 | Date: 6/19/2019