

Inspection Photos

API: 05-071-09061

Operator: ARP PRODUCTION COMPANY
WAPITI OPERATING LLC

Inspection Date: 6/19/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 6/19/2019

Inspection Photos



Photo 1. There is List B noxious weeds growing along the main & access road to the location. (Musk thistle shown in photo)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 6/19/2019

Inspection Photos



Photo 2. There is erosion occurring down the road and no BMP's are installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 6/19/2019

Inspection Photos



Photo 3. Well sign is installed. New operator name has not been changed yet.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 6/19/2019

Inspection Photos



Photo 4. There is signs of erosion occurring from the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 6/19/2019

Inspection Photos



Photo 5. There are noxious weeds (Musk, Canada thistle) growing along the the fill slope and cut slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 6/19/2019