

Inspection Photos

Location Name: Cass 7-62 15-1H Location ID 422622, Spill ID #465524

Inspection Date: 6/20/2019



Photo 1 – Excavation at rear of produced water fiberglass AST



Photo 2 – Photo of dumplines and adjacent excavation at rear of produced water fiberglass AST.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources