

Inspection Photos

06/20/2019

Operator: MURFIN DRILLING COMPANY INC -
61650

Location ID: 387013
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: MURFIN DRILLING COMPANY INC - 61650

Location ID: 387013



Photo 1: Photo taken from the north end of the location, facing east. Photos 1-3 provide an overview of the location from east, to south, to west. Photos show additional reclamation activities appear to have been conducted.

Inspection Photos

Operator Name: MURFIN DRILLING COMPANY INC - 61650

Location ID: 387013



Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: MURFIN DRILLING COMPANY INC - 61650

Location ID: 387013



Photo 3: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: MURFIN DRILLING COMPANY INC - 61650

Location ID: 387013



Photo 4: Photo taken from the southwest end of the location, facing southwest. Photo shows stormwater runoff is beginning to cause erosion degradation with sediment discharge onto the adjacent lands. Advise installing BMPs



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: MURFIN DRILLING COMPANY INC - 61650

Location ID: 387013



Photo 5: Photo taken from the southwest end of the location, facing northeast. Photo shows stormwater runoff is beginning to cause erosion degradation with sediment discharge onto the adjacent lands. Advise installing BMPs