

Inspection Photos

06/20/2019

Operator: PRONGHORN OPERATING LLC -
10422

Location ID: 438713
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: PRONGHORN OPERATING LLC - 10422

Location ID: 438713



Photo 1: Photo taken from the central area of the location, facing north. Photos 1-4 provide an overview of the location from north, to south, to east, to west. Photos show vegetation over the reclamation area. Vegetation observed is predominantly undesirable weedy plant species (such as Kochia, Amaranth, Chenopodium and Salsola sp), and annual forbs. Unable to find evidence that additional reclamation/seeding activities have been conducted, or stabilization controls installed per corrective actions.



Inspection Photos

Operator Name: PRONGHORN OPERATING LLC - 10422

Location ID: 438713



Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: PRONGHORN OPERATING LLC - 10422
Location ID: 438713



Photo 3: See comments under photo 1.



Inspection Photos

Operator Name: PRONGHORN OPERATING LLC - 10422

Location ID: 438713




Photo 4: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: PRONGHORN OPERATING LLC - 10422

Location ID: 438713



Photo 5: Photo taken from the east-central area of the location, facing west. Photo shows germination survey transect #1 conducted on the location.

Inspection Photos

Operator Name: PRONGHORN OPERATING LLC - 10422

Location ID: 438713



Photo 6: Photo taken from the 50th point of germination survey transect #1. Vegetation seen in photo include *Helianthus annuus*, *Chenopodium* sp., and *Kochia*. Very little desirable perennial vegetative germination and establishment observed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: PRONGHORN OPERATING LLC - 10422

Location ID: 438713



Photo 7: Photo taken from the south-central area of the location, facing north. Photo shows germination survey transect #2 conducted on the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: PRONGHORN OPERATING LLC - 10422

Location ID: 438713



Photo 8: Photo taken from the 50th point of germination survey transect #2. Vegetation seen in photo include *Helianthus annuus*, *Chenopodium* sp., and *Kochia*. Very little desirable perennial vegetative germination and establishment observed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: PRONGHORN OPERATING LLC - 10422

Location ID: 438713



Photo 9: Photo taken from the adjacent reference area. Photo shows reference vegetation to compare to vegetation on the location.