

Tranco 5A  
API: 05-103-05320  
Inspection: 679704581



Photo 1. Pump jack.



Tranco 5A  
API: 05-103-05320  
Inspection: 679704581



**Photo 2. Separator.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Tranco 5A  
API: 05-103-05320  
Inspection: 679704581



Photo 3. Tank battery.





Tranco 5A  
API: 05-103-05320  
Inspection: 679704581



**Photo 4. Building by storage tanks.**

Tranco 5A  
API: 05-103-05320  
Inspection: 679704581



Photo 5. Interior of building.



Tranco 5A  
API: 05-103-05320  
Inspection: 679704581



Photo 6. Unused sphere.



Photo 7. Unused timbers.

Tranco 5A  
API: 05-103-05320  
Inspection: 679704581



**Photo 8. Chemical / grease / fuel containers in building.**



**Photo 9. Chemical containers in building.**