

Inspection Photos
Location Name: Matrix Pad
Location ID: 333309



Photo 1 – Separators



Photo 2 – Tank Battery

Inspection Photos
Location Name: Matrix Pad
Location ID: 333309



Photo 3 – Matrix 21-29 Wellhead

Photo 4 – Wellhead sign on ground

Inspection Photos
Location Name: Matrix Pad
Location ID: 333309



Photo 5 – Matrix 11-29 Wellhead

Photo 6 – Wording on Wellhead sign has faded no longer legible.

Inspection Photos
Location Name: Matrix Pad
Location ID: 333309



Photo 7 – Matrix 12-29 PNA'd



Photo 8 – Matrix CNW-29 PNA'd

Inspection Photos
Location Name: Matrix Pad
Location ID: 333309



**Photo 7 – Produced Water Vault; missing Capacity Content
and missing NFPA signage**