

Inspection Photos

Location Name: Babb 15-14 Tank Battery and Pit, Location ID 327704, Pit ID 110637

Inspection Date: 6/20/2019



Photo 1 – View of former Babb 15-14 production facility from Weld County Road 68, looking north.



Inspection Photos

Location Name: Babb 15-14 Tank Battery and Pit, Location ID 327704, Pit ID 110637

Inspection Date: 6/20/2019



Photo 2 – View of oily material stored on former Babb 15-14 production facility location, looking east.



Inspection Photos

Location Name: Babb 15-14 Tank Battery and Pit, Location ID 327704, Pit ID 110637

Inspection Date: 6/20/2019



Photo 3 – View of former Babb 15-14 production facility, looking west.



Inspection Photos

Location Name: Babb 15-14 Tank Battery and Pit, Location ID 327704, Pit ID 110637

Inspection Date: 6/20/2019



Photo 4 – View of oily waste stored on plastic on former Babb 15-14 production facility location.



Inspection Photos

Location Name: Babb 15-14 Tank Battery and Pit, Location ID 327704, Pit ID 110637

Inspection Date: 6/20/2019



Photo 5 – View of oily waste stored on plastic on former Babb 15-14 production facility location.



Inspection Photos

Location Name: Babb 15-14 Tank Battery and Pit, Location ID 327704, Pit ID 110637

Inspection Date: 6/20/2019



Photo 6 – View of oily waste stored on plastic on former Babb 15-14 production facility location.



Inspection Photos

Location Name: Babb 15-14 Tank Battery and Pit, Location ID 327704, Pit ID 110637

Inspection Date: 6/20/2019



Photo 7 – View of oily waste stored on plastic on former Babb 15-14 production facility location.



Inspection Photos

Location Name: Babb 15-14 Tank Battery and Pit, Location ID 327704, Pit ID 110637

Inspection Date: 6/20/2019



Photo 8 – Debris remains on location at former Babb 15-14.



Inspection Photos

Location Name: Babb 15-14 Tank Battery and Pit, Location ID 327704, Pit ID 110637

Inspection Date: 6/20/2019



Photo 9 – Overview of former Babb 15-14 well pad looking north.

