

Inspection Photos
Location Name: Nessu #15
Location ID: 317831



Colorado Oil and Gas Conservation Commission
40.12202, -104.79752, 1476.9m
Jun 24, 2019 10:25:50

Photo 1 WH



Colorado Oil and Gas Conservation Commission
40.12203, -104.79757, 1476.6m
Jun 24, 2019 10:26:19

Photo 2 WH sign does not reflect current operator and emergency contact number.

Inspection Photos
Location Name: Nessu #15
Location ID: 317831



Photo 3 Mechanical issue: Packing appears to be leaking and stained soil around WH



Photo 4 WH approximately 50 yds from residents house.