

Pit Status Evaluation Form

Pit Overview:

Pit Name: CLAYTON WYMAN	Facility ID: 113816
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: CHAPARRAL RESOURCES INC / 16250	
Updated Operator: STARLIGHT RESOURCES LLC - 81825	
Form 15 Pit Permit Doc #: NA	Permit Date: NA
Related Facilities: API # 05-001-07589 (Facility ID 202184), Location 376319	

County: Adams			
Township: 1S	Range: 67W	Section: 6	QQ: NESE
Original Latitude/ Longitude: 39.988019 / -104.924303			
Updated Latitude/ Longitude: 39.993287 / -104.9225			
Basis for Location Change:			
Location updated based on aerial imagery (circa 1993).			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|------------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: NA | Date: NA |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 698382 | Date: 2/27/1989 |
| | Doc #: 339965 | Date: 8/8/1995 |
| | Doc #: 200026994 | Date: 05/30/2002 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

Well PA 3/20/2001, passed final inspection 5/30/2002.

Pit Status Review Summary:

Inspections document an unlined pit on location, which was replaced by a cement vault prior to 8/8/1995 inspection. Well was plugged and passed final reclamation inspection 5/30/2002. Pit status has been changed to Closed.



