

Inspection Photos
Location Name: BTA Federal 12-33
API: 05-081-06971



Photo 1. Overview of location taken at entrance facing west.



Photo 2. Stained soil and unmarked risers.

Inspection Photos
Location Name: BTA Federal 12-33
API: 05-081-06971



Photo 3. Close up of unmarked risers and stained soil from photo 2.



Photo 4. Bird nest with bird in nest on produced water catwalk.