

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/24/2019

Submitted Date:

06/24/2019

Document Number:

692602056

FIELD INSPECTION FORM

Loc ID 321674 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77269

Findings:

17 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Elsom, Lee Ann	281-891-1577	lelsom@cogc.com	
Rogers, Bob	719-767-8851	brogers@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207741	WELL	PR	12/21/2010	OW	017-06676	WECO-UPRC WILLIAM 13-11 1	PR

General Comment:

[Routine Inspection](#)

Location			
Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks and treaters. Stickers on water tank need replaced		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign by treaters		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Metal panels around oil tanks. Metal panels around water tank		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Metal panels around treaters		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	
Equipment:			
Type: Prime Mover	# 1		corrective date
Comment:	Ford 300-6 motor		
Corrective Action:		Date:	

Type: Vertical Separator	# 2		
Comment:	2-Vertical gas separators w/sheds		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Gas scrubber and day drum in metal shed, solar powered cathodic rectifier		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 0		
Comment:	Removed from location		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Parkersburg 320		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		38.931810,-103.088640
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		38.931480,-103.088900
Comment:	Water tank is west of treaters				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	HEATED STEEL AST		38.931810,-103.088640
Comment:	South oil tank is a heated steel tank				
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shared berms				
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 207741 Type: WELL API Number: 017-06676 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central tank battery for \(Weco-Williams 13-11 & 31-11 #7\[TA\]\) 1000' N @ 38.931810/-103.088640](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT