

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/25/2019

Submitted Date:

06/25/2019

Document Number:

692602065

FIELD INSPECTION FORM

Loc ID 337736 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 55575
Name of Operator: MCELVAIN ENERGY INC
Address: 511 16TH STREET SUITE 700
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Cooper, Tony	(303) 893-0933 x331	tony.cooper@mcelvain.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288368	WELL	PR	09/30/2007	GW	125-10541	RAVEN 3-11	PR

General Comment:

Routine Inspection

Location			
Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	Stickers on chemical tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by VGS		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Metal panels around pipeline riser		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around wellhead, meter shed, metal shed and VGS		
Corrective Action:		Date:	
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Telemetry equipment, gas scrubber and chemical tank w/containment		
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:	1-Vertical gas separator in metal shed 1-Vertical gas separator 50% buried by meter shed		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Churchill unit. Horsehead removed and stored neatly on location		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 288368 Type: WELL API Number: 125-10541 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Horsehead and bridle removed from unit and free flowing at time of inspection](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT